

AD-A078 884

GANNETT FLEMING CORDRY AND CARPENTER INC HARRISBURG PA F/G 13/13
NATIONAL DAM INSPECTION PROGRAM. PA-468 DAM (NDI ID NUMBER PA-0--ETC(U)
AUG 79 F FUTCHKO DACW31-79-C-0015


UNCLASSIFIED

NL

OF
AD
A078884



END
DATE
FILMED
1-80
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD A078884

Distribution Unlimited
Approved for Public Release
Contract No. DACW31-79-C-0015

DDC FILE COPY

DISCLAIMER NOTICE

1

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

⑥ Number
National Dam Inspection Program.
PA-468 Dam (NDI-I.D. PA-00046,
DER-I.D. 58-132, SCS-ID, PA-468),
SUSQUEHANNA RIVER BASIN,
BROOKLYN RUN, SUSQUEHANNA COUNTY,
PENNSYLVANIA. Phase I Inspection
Report,
Number ②

PA-468 Dam

NDI ID No. PA-00046

DER ID No. 58-132

SCS ID No. PA-468

SUSQUEHANNA COUNTY COMMISSIONERS

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

⑩ Frederick / Futch KO

Prepared by

GANNETT FLEMING CORDDRY AND CARPENTER, INC.

Consulting Engineers

P.O. Box 1963

Harrisburg, Pennsylvania 17105

For

⑮ DACW31-79-C-0015

DEPARTMENT OF THE ARMY

Baltimore District, Corps of Engineers

Baltimore, Maryland 21203

⑪ AUGUST 1979

⑫ 79

This document has been approved
for public release and sale; its
distribution is unlimited.

411 004

JOB

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

SUSQUEHANNA RIVER BASIN
BROOKLYN RUN, SUSQUEHANNA COUNTY
PENNSYLVANIA
PA-468 Dam

NDI ID No. PA-00046
DER ID No. 58-132
SCS ID No. PA-468

SUSQUEHANNA COUNTY COMMISSIONERS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

AUGUST 1979

CONTENTS

<u>Description</u>	<u>Page</u>
SECTION 1 - Project Information	1
SECTION 2 - Engineering Data	7
SECTION 3 - Visual Inspection	9
SECTION 4 - Operational Procedures	11
SECTION 5 - Hydrology and Hydraulics	12
SECTION 6 - Structural Stability	15
SECTION 7 - Assessment, Recommendations, and Proposed Remedial Measures	16

ACQUISITION FOR	<input checked="" type="checkbox"/>
WALL, GATE	<input type="checkbox"/>
DOE TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	<input type="checkbox"/>
By	
Distribution	
Availability codes	
Avail and/or special	
Dist.	23
	A

PLATES

<u>Plate</u>	<u>Title</u>
1	Location Map.
2	Plan and Typical Section.
3	Alignment Plan.
4	Profiles.
5	Drain Plan.
6	Main Spillway and Outlet Works.
7	Main Spillway Riser.
8	Diversion System.

APPENDICES

<u>Appendix</u>	<u>Title</u>
A	Checklist - Engineering Data.
B	Checklist - Visual Inspection.
C	Hydrology and Hydraulics.
D	Photographs.
E	Geology.

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT OF GENERAL CONDITION

AND

RECOMMENDED ACTION

Name of Dam: PA-468 Dam
NDI ID No. PA-00046/DER ID No. 58-132
SCS ID No. PA-468

Owner: Susquehanna County Commissioners

State Located: Pennsylvania

County Located: Susquehanna

Stream: Brooklyn Run

Date of Inspection: 18 July 1979

Inspection Team: Gannett Fleming Corddry and
Carpenter, Inc.
Consulting Engineers
P.O. Box 1963
Harrisburg, Pennsylvania 17105

Based on visual inspection, available records, calculations and past operational performance, PA-468 Dam is judged to be in good condition. The existing spillway can pass the Probable Maximum Flood (PMF) without overtopping of the dam. The spillway capacity is rated as adequate.

There is a slope stability analysis for the embankment, and it indicates that the embankment has adequate factors of safety. There is no evidence of significant problems threatening the embankment.

The following measures are recommended to be undertaken by the Owner, in approximate order of priority, without delay:

(1) The Owner should request the SCS to verify that the design data upon which this report is based is, as assumed, valid. If other information is found to exist, the conclusions reached in this study should be checked for validity.

(2) Make repairs necessary to eliminate the separation and leakage between the main spillway conduit and the impact basin headwall.

(3) Remove rocks from the impact basin.

(4) Remove brush from the embankment and the auxiliary spillway.

In addition, it is recommended that the Owner modify his operational procedures as follows:

(1) Develop a detailed emergency operation and warning system for PA-468 Dam.

(2) Provide round-the-clock surveillance of PA-468 Dam during periods of unusually heavy rains.

(3) When warnings of a storm of major proportions are given by the National Weather Service, the Owner should activate his emergency operation and warning system procedures.

Submitted by:

CANNETT FLEMING CORDDRY
AND CARPENTER, INC.


A handwritten signature of Frederick Futchko in dark ink, written over a horizontal line.

FREDERICK FUTCHKO
Project Manager, Dam Section

Date: 17 September 1979

Approved by:

DEPARTMENT OF THE ARMY
BALTIMORE DISTRICT, CORPS OF
ENGINEERS

A handwritten signature of James W. Peck in dark ink, written over a horizontal line. The signature is stylized and includes a large initial 'J'.

JAMES W. PECK
Colonel, Corps of Engineers
District Engineer

Date: 25 Sep 79

PA-468 DAM



Overview

SUSQUEHANNA RIVER BASIN
BROOKLYN RUN, SUSQUEHANNA COUNTY
PENNSYLVANIA

PA-468 Dam

NDI ID No. PA-00046
DER ID No. 58-132
SCS ID No. PA-468

SUSQUEHANNA COUNTY COMMISSIONERS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

SECTION 1

PROJECT INFORMATION

1.1 General.

a. Authority. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. Purpose. The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. The dam consists of a homogeneous earthfill embankment that is 680 feet long and 64 feet high at its maximum section. The main spillway is a drop spillway located near the left abutment of the dam. It consists of a concrete riser connected to a 30-inch diameter reinforced concrete pipe under the embankment.

One 12-inch by 21-inch uncontrolled orifice is located in the upstream face of the concrete riser with the orifice crest at El. 1227.0, which is 27 feet below design elevation of the top of the dam. The top of the riser is 8 feet below the design elevation of the top of the dam. A platform and trashrack are located above the riser. The outlet works is located at the main spillway. It consists of a 12-inch diameter steel pipe. The outlet works is closed off by a steel plate bolted into place at the downstream end of the pipe.

The auxiliary spillway is an excavated channel at the right abutment of the dam. It is grass-lined except for portions that were excavated into rock. At the control section, the auxiliary spillway has an earthen crest that is 75 feet long and 5.4 feet below the design elevation of the top of the dam and 2.6 feet above the crest of the main spillway. The various features of the dam are shown on the Plates at the end of the report and on the Photographs in Appendix D.

The total drainage area at the dam is 0.38 square mile; about 0.08 square mile of the drainage area is drained by a diversion ditch system.

b. Location. The dam is located on Brooklyn Run approximately 0.1 mile north of Brooklyn, Susquehanna County, Pennsylvania. PA-468 Dam is not shown on current USGS maps, because it was recently constructed. The coordinates of the dam are N41°45'20" -W75°48'25". The location map is shown on Plate 1.

c. Size Classification. Intermediate (64 feet high, 65 acre-feet).

d. Hazard Classification. High hazard. Downstream conditions indicate that a high hazard classification is warranted for PA-468 Dam. (Paragraph 5.1c. (5)).

e. Ownership. Susquehanna County Commissioners. *It is owned by the*

f. Purpose of Dam. Flood control. *Purpose is for*

g. Design and Construction History. PA-468 Dam was planned under an agreement between the Susquehanna County Commissioners (SCC-Owner) and the Soil Conservation Service of the U.S. Department of Agriculture (SCS). Under this agreement, the Owner acquired title to the land, the SCS designed and funded construction of the dam, and the SCC maintains the dam. The dam was designed

between 1964 and 1965 by the SCS. The permit to construct the dam was issued in 1965 and construction was started in May 1966. The Contractor was A.F. Costanzo and Sons, Scranton, Pennsylvania. Construction of the dam was under the supervision of Jesse Evans, contracting officer for SCC, and Henry Hurt, resident inspector for the SCS. The dam was completed in 1967.

h. Normal Operational Procedure. The reservoir is normally maintained at the crest of the orifice in the main spillway riser. The bolted-plate closure on the outlet works is normally in place.

1.3 Pertinent Data.

a.	<u>Drainage Area.</u> (square miles)	0.38
b.	<u>Discharge at Damsite.</u> (cfs)	
	Maximum known flood at damsite	Unknown
	Spillway capacity.	
	Orifice with pool at main spillway riser crest	40
	Main spillway with pool at auxiliary spillway crest	143
	Auxiliary spillway with pool at top of dam	2,775
c.	<u>Elevation.</u> (feet above msl)	
	Top of dam (design)	1254.0
	Maximum pool (design)	1252.0
	Normal pool (main spillway orifice crest)	1227.0
	Upstream invert outlet works	1214.0
	Downstream invert outlet works	1190.0
	Streambed at toe of dam	1190.0
d.	<u>Reservoir Length.</u> (miles)	
	Normal pool	0.03
	Maximum pool	0.11
e.	<u>Storage.</u> (acre-feet)	
	Normal pool	3
	Maximum pool	65
f.	<u>Reservoir Surface</u> (acres)	
	Normal pool	0.4
	Maximum pool	4.2

g.	<u>Dam.</u> <u>Type</u>	Homogeneous earthfill
	<u>Length (feet)</u>	680
	<u>Height (feet)</u>	64
	<u>Topwidth (feet)</u>	17
	<u>Side Slopes</u> Upstream	1V on 3.5H. There is a 10-foot sloping berm at El. 1228.0.
	Downstream	1V on 2H
	<u>Zoning</u>	None
	<u>Cutoff</u>	Impervious fill in cutoff trench.
	<u>Grout Curtain</u>	None
h.	<u>Diversion and Regulating Tunnel</u>	None
i.	<u>Spillway.</u> <u>Main (Principal or Service)</u> <u>Spillway</u>	
	<u>Type</u>	Drop spillway. Vertical rectangular riser 2.5 feet by 7.5 feet, with rounded crest; one 1-foot high by 1.75-foot long orifice located on upstream face of riser. Riser connects to conduit.

i. Spillway. (continued)

Length of Weir (feet)

Orifice

One at 1.75

Riser

Two at 7.5

Crest Elevation

Orifice

1227.0

Top of riser

1246.0

Upstream Channel

Reservoir; a platform is 1.75 feet above the riser.

Conduit

Type

Reinforced concrete pipe, 2.5 feet in dia., on concrete cradle.

Length (feet)

231.9

Elevation

Upstream invert
at riser

1204.0

Downstream invert

1190.0

Downstream Channel

Impact basin at natural stream.

Auxiliary (Emergency) Spillway

Type

Grass-lined earthen and rock cut with 1V on 2H side slopes.

Length of Weir (feet)

75 at earthen control section.

Crest Elevation

1248.6

Upstream Channel

Grass-lined channel to reservoir.

i. Spillway. (continued)

Downstream Channel

Grass-lined
channel
extending to
overbank.
Left slope
has riprap.

j. Regulating Outlets.
Type

Steel pipe,
12-inch
dia.,
extending to
main spillway
riser.

Length (feet).

44

Closure

Bolted-plate
closure in
riser at
downstream
end of steel
pipe.

Access

Hatch in
platform
above main
spillway
riser.

SECTION 2

ENGINEERING DATA

2.1 Design.

a. Data Available. A summary of the available design data is in Appendices A and C. The SCS design folder for PA-468 Dam, which normally contains specifications, hydrologic and hydraulic design computations, results of geologic investigations and soils testing, slope stability analyses, and structural design computations, was not available in PennDER's files. It was available in the SCS files. Upon examination, it was found that each section of the design folder, except the hydrologic and hydraulic design section, contained a cover sheet with "void" marked on it. SCS personnel said that they were unaware of the actual status of the information and did not know why it was marked void. They stated that they would conduct further research and contact Gannett Fleming Corddry and Carpenter, Inc. (GFCC) if additional information could be found. No additional information became available to GFCC.

b. Design Features. The dam and appurtenances are described in Paragraph 1.2a. The design features are shown on the Plates at the end of the report and on the Photographs in Appendix D. The embankment is shown on Plates 2, 3, and 4, and on Photographs A, B, and C. A plan of the subdrainage system is shown on Plate 5.

The main spillway riser is shown on Plates 6 and 7 and on Photograph C. The impact basin is shown on Plates 2, 3, and 4 and on Photograph D. The watershed diversion system is shown on Plate 8.

c. Design Considerations. Although the main spillway design has been used successfully by the SCS for many years, it appears that the entrance to the conduit could possibly develop cavitation during certain flow conditions. Other design considerations are discussed in Sections 5 and 6.

2.2 Construction.

a. Data Available. Construction data available consist of the construction specifications, construction photographs, and reports both from the resident inspector and from the periodic construction inspections by the Commonwealth. No adverse items were noted in any of these

reports. The project was reported to have been constructed in accordance with the approved plans and specifications.

b. Construction Considerations. The available information indicates that the dam is well constructed.

2.3 Operation. Records of operation consist of reports of annual inspections conducted by the SCS and SCC. Based on these reports, all structures have performed satisfactorily, and only normal maintenance has been necessary.

2.4 Evaluation.

a. Availability. Engineering data were provided by the Bureau of Dams and Waterway Management, Department of Environmental Resources, Commonwealth of Pennsylvania (PennDER), and by the SCS. A SCC representative was available for information during the inspection. The SCS also researched the files for additional information upon request of the inspection team.

b. Adequacy. The type and amount of design data and other engineering data are good. The assessment is based on the combination of design data, visual inspection, and performance history.

c. Validity. There is no reason to question the validity of the available construction and operation data. Although the validity of the available design data is in question, due to being marked "void", GFCC could find no apparent changes between the aforementioned available design data and the approved plans.

SECTION 3
VISUAL INSPECTION

3.1 Findings.

a. General. The overall appearance of the dam is good with a few deficiencies as noted herein. The locations of deficiencies are shown in Appendix B on Plate B-1. Survey data acquired during this inspection are presented in Appendix B. Datum for the survey was assumed at the design elevation of the end sill of the impact basin, El. 1190.00. On the day of the inspection, the pool was 0.1 foot above the crest of the orifice in the main spillway riser.

b. Embankment. The embankment is in good condition. The grass cover on the upstream slope and the crownvetch cover on the downstream slope are in excellent condition. There is no slope protection on the upstream slope other than the grass cover. A survey performed for this inspection showed that embankment lines and grades are in good conformance with the design lines and grades. Two foundation drain outlets, located at the impact basin, each had a slight, clear flow. Two small shrubs were growing on the downstream slope of the dam.

c. Appurtenant Structures. The outlet works was submerged and could not be inspected. The bolted-plate closure in the riser at the end of the 12-inch diameter outlet works pipe could not be inspected due to flowing water in the riser.

The main spillway riser was in good condition. The reinforced concrete outlet conduit was inspected and found to be in good condition. Joint separations, up to a maximum of 1 inch, were observed along the conduit. The joint separations were nearly zero at each end and increased progressively toward the maximum section of the dam. At its downstream end, the reinforced concrete outlet conduit was slightly separated from the impact basin headwall. A slight, clear flow of water was visible at the separation. The impact basin contained several large rocks, apparently the result of vandals. There was some minor spalling of the concrete along the inside of the left wall of the impact basin.

The auxiliary spillway was in good condition. A minor amount of brush was growing in the approach area, but no other deficiencies were noted. The survey indicated that the difference in elevation between the auxiliary spillway crest and the top of the dam was consistent with the design difference.

d. Reservoir Area. The reservoir area has steep, grassed slopes, and it is utilized as a pasture. The watershed is nearly all farmland with only minor development. The watershed diversion system was generally in good condition, except that the inlet area for the 54-inch diameter culvert was overgrown with brush.

e. Downstream Channel. Brooklyn Run flows for a distance of 0.4 mile downstream from the dam to its confluence with Hop Bottom Creek. The Village of Brooklyn is situated along Brooklyn Run from 0.1 mile to 0.4 mile downstream from the dam. There are approximately 25 low-lying dwellings along this reach. The access road to the dam is a public road along the left abutment.

SECTION 4

OPERATIONAL PROCEDURES

4.1 Procedure. The reservoir is maintained at the crest of the orifice in the main spillway riser, Elevation 1227.0, with excess inflow discharging over the spillway and into Brooklyn Run, which flows into Hop Bottom Creek about 0.4 mile downstream. A 30-inch diameter reinforced concrete conduit discharges water from the reservoir. Since the 12-inch diameter outlet works pipe is intended only for drawing down the reservoir, the bolted-plate closure on its downstream end, located in the riser, is usually in place.

4.2 Maintenance of Dam. There are no designated caretakers for the dam. The SCC, with the assistance of the SCS, makes a formal inspection of the dam each year, and the records are filed. Maintenance deficiencies are corrected shortly after the inspection. Informal inspections are also made when the SCC representative is on the site for other reasons.

4.3 Maintenance of Operating Facilities. There are no gates or other operating facilities.

4.4 Warning Systems in Effect. The SCC Representative stated that there was no emergency operation and warning plan. He did state that the condition of the dam is checked during heavy rains.

4.5 Evaluation of Operational Adequacy. Maintenance of the dam is good. The procedures used to inspect the dam are good, as is the correction of maintenance deficiencies. An emergency operation and warning system is a necessary safeguard to improve the safety of the dam and prevent loss of life downstream, should evidence of stress develop at the dam.

SECTION 5

HYDROLOGY AND HYDRAULICS

5.1 Evaluation of Features.

a. Design Data. The hydrology and hydraulics of the design of the dam were based on standard SCS criteria. The crest of the orifice in the main spillway riser was determined by sediment requirements. The crest elevation of the main spillway riser and the crest elevation of the auxiliary spillway were set by routing 100-year storms based on SCS procedures. The design high water level was determined by routing a storm equal to 1.25 times the 100 year, 6-hour storm. The top of dam elevation and auxiliary spillway size were determined by routing the "Freeboard" storm, which is equal to twice the design high water storm (2.5 times the 100-year, 6-hour storm). The "Freeboard" storm is discussed in Paragraph 5.1d.

b. Experience Data. The maximum flood at the damsite is unknown.

c. Visual Observations.

(1) General. The visual inspection of PA-468 Dam, which is described in Section 3, resulted in some observations relevant to hydrology and hydraulics. These observations are evaluated herein for the various features.

(2) Embankment. The slope protection on the upstream slope is dense grass. Although there is no riprap, the erosion potential due to wave action is minimal. The combination of small maximum pool (4.2 acres) and dense vegetal cover makes erosion unlikely. In addition, the good maintenance record for the dam indicates that any minor erosion that might occur would be repaired promptly.

(3) Appurtenant Structures. Although joint separations as large as 1 inch were present in the 30-inch main spillway conduit, the Specifications indicate that the pipe joints have a minimum extensibility of 2 inches. Therefore, the joint openings are less than the allowable openings, and the joints should be watertight. The connection of the outlet conduit to the impact basin headwall is not watertight. Although this condition has apparently not resulted in any adverse effects, it is considered to be undesirable. Potentially adverse

conditions, such as possible loss of fine filter material, might occur under high head conditions. The large rocks in the impact basin are also considered to be undesirable. During periods of high spillway discharge, turbulence might cause the rocks to damage the impact basin. The amount of brush in the auxiliary spillway is not significant at the present time, but control of it is necessary to insure that no reduction of spillway capacity occurs.

(4) Reservoir Area. No conditions were observed in the reservoir area or watershed that might present significant hazard to the dam. The assessment of the dam is based on existing conditions, and the effects of future development are not considered.

(5) Downstream Conditions. No conditions were observed immediately downstream from the dam that would create significant hazard to the dam. If the dam should fail, a hazard would exist to dwellings in the Village of Brooklyn. Because of the possibility of flooding dwellings, a high hazard classification is warranted for PA-468 Dam. The SCS designed the dam assuming that it was a Class C structure. This is essentially equivalent to a high hazard classification. Access to PA-468 Dam is excellent.

d. Overtopping Potential.

(1) Spillway Design Flood. According to the criteria established by the Office of the Chief of Engineers (OCE) for the size (Intermediate) and hazard potential (High) of PA-468 Dam, the Spillway Design Flood (SDF) is the Probable Maximum Flood (PMF).

(2) Design Storm. The SCS "Freeboard" storm, which was used to determine the size of the auxiliary spillway and the top elevation of the dam, was not developed from PMF methods. However, the total rainfall of 24.5 inches is equivalent to a PMF rainfall for this area. The assumed losses of 3.3 inches are slightly higher than those established by criteria for the Susquehanna Basin, but the unit hydrograph used by the SCS is conservative. The computed peak inflow of 2,734 cfs is equivalent to a PMF peak inflow. The storm is an acceptable estimate of the PMF.

(3) Design Storm Computations. The design storm computations and the spillway capacity computations are in Appendix C. It is noted that the auxiliary

spillway alone has sufficient capacity to pass the "Freeboard" storm peak flow without routing the flow. Therefore, the spillway can pass the PMF without any overtopping of the dam.

(4) Spillway Adequacy. The criteria used to rate the spillway adequacy of a dam are described in Appendix C. Since PA-468 Dam can pass the PMF, the spillway capacity is rated as adequate.

SECTION 6
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability.

a. Visual Observations. Nothing was noted during the visual inspection that was considered to adversely reflect on the stability of the dam or its appurtenant structures.

b. Design and Construction Data. Stability analyses were performed by the SCS during the design of the dam. The results of the analyses are included in Appendix A. The factors of safety for the upstream slope were computed to be 1.12 considering horizontal flow and 1.20 considering parallel flow. The factors of safety for the downstream slope were computed to be 1.25 for an infinite slope analysis with a dry slope condition and 3.0 using a wedge analysis. The design shear strength was based on the consolidated-undrained strength obtained from a triaxial shear test. These factors of safety are considered to be adequate.

c. Operating Records. The reports of previous inspections indicate that no stability problems have occurred over the operational history of the dam.

d. Postconstruction Changes. There have been no postconstruction changes to PA-468 Dam.

e. Seismic Stability. PA-468 Dam is located in Seismic Zone 1. Normally, it can be considered that if a dam in this zone has adequate factors of safety under static loading conditions, it can be assumed safe for any expected earthquake loading. Since the factors of safety are adequate, the dam is assumed to be stable for any expected earthquake loading.

SECTION 7
ASSESSMENT, RECOMMENDATIONS, AND
PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety.

(1) Based on visual inspection, available records, calculations, and past operational performance, PA-468 Dam is judged to be in good condition. The spillway can pass the PMF without overtopping of the dam. The spillway capacity is rated as adequate.

(2) There is a stability analysis for the embankment, and it indicates that the embankment has adequate factors of safety. There is no evidence of significant problems threatening the embankment.

(3) The visual inspection revealed some deficiencies, which are summarized below for the various features.

<u>Feature and Location</u>	<u>Observed Deficiencies</u>
<u>Embankment:</u>	
Downstream Slope	Minor amount of brush.
<u>Main Spillway:</u>	
Conduit	Conduit joints separated; slight separation of conduit from impact basin headwall with slight, clear leakage.
Impact Basin	Rocks in impact basin; minor spalling of concrete.
<u>Auxiliary Spillway:</u>	Minor amount of brush.

b. Adequacy of Information. The information available is such that an assessment of the condition of the dam can be inferred from the combination of visual inspection, past performance, and computations performed prior to and as part of this study.

c. Urgency. The recommendations in Paragraph 7.2 should be implemented without delay.

d. Necessity for Further Investigations. In order to accomplish some of the remedial measures outlined in Paragraph 7.2, further investigations by the Owner will be required.

7.2 Recommendations and Remedial Measures.

a. The following measures are recommended to be undertaken by the Owner, in approximate order of priority, without delay:

(1) The Owner should request the SCS to verify that the design data upon which this report is based is, as assumed, valid. If other information is found to exist, the conclusions reached in this study should be checked for validity.

(2) Make repairs necessary to eliminate the separation and leakage between the main spillway conduit and the impact basin headwall.

(3) Remove rocks from the impact basin.

(4) Remove brush from the embankment and the auxiliary spillway.

b. In addition, it is recommended that the Owner modify his operational procedures as follows:

(1) Develop a detailed emergency operation and warning system for PA-468 Dam.

(2) Provide round-the-clock surveillance of PA-468 Dam during periods of unusually heavy rains.

(3) When warnings of a storm of major proportions are given by the National Weather Service, the Owner should activate his emergency operation and warning system procedures.

SUSQUEHANNA RIVER BASIN
BROOKLYN RUN, SUSQUEHANNA COUNTY
PENNSYLVANIA

PA-468 Dam

NDI ID No. PA-00046
DER ID No. 58-132
SCS ID No. PA-468


SUSQUEHANNA COUNTY COMMISSIONERS

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

AUGUST 1979

PLATES



ALOP _____ FOR _____
SEE REPORT _____
_____ Div 5

ELEVATION DATA
E DAW STA 4+40 TO STA 8+00
SEE SHEET 7 FOR DETAILS

STONE WALL REMOVAL 912'
FENCE REMOVAL 90'
FENCE REMOVAL C DRAINAGE 90'
(SPEC 3)

1991

	STONE WALL
	EXISTING FENCE
	FENCE TO BE REMOVED
	STONE WALL TO BE REMOVED
	FENCE REMOVAL CHANGE
	NEW FENCE TO BE INSTALLED
	SOIL TEST PIT
	TP
	ACCESS PIT, REMOVABLE POLE TO BE CLEARED & N.A.

FOR FIVE COPIES SEE SHEET 13.

SEP 14 1965

C. H. McConnell
Chief Engineer

CUBIC YARDS	BEFORE	AFTER
710	1215.0	1220.0
270	1220.0	1225.0
678	1225.0	1230.0
5970	1230.0	1235.0
45.0	1235.0	1240.0
1310	1240.0	1245.0
1522	1245.0	1250.0

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

[Faint handwritten notes or bleed-through from the reverse side of the page.]

PA-468-P

PLATE 2

SIX SHEETS 2 6 12 FOR 1203
OF BRICK WORKS AND TEST PITS.

2



EMERGENCY SPILLWAY & CURVE DATA

UPSTREAM CURVE



$I = 80.00'$
 $R = 92.5'$
 $T = 77.42'$
 $Lc = 129.15'$
 $CH = 110.32'$
 $M = 21.69'$
 $E = 20.25'$
 $PC = \text{STATION } 2+70.05$
 $PT = \text{STATION } 4+00.00$

DOWNSTREAM CURVE


$I = 55.00'$
 $R = 92.5'$
 $T = 52.35'$
 $Lc = 96.25'$
 $CH = 91.10'$
 $M = 11.95'$
 $E = 18.77'$
 $PC = \text{STATION } 4+03.00$
 $PT = \text{STATION } 5+70.25$

STATION ELEVATION CHORD	
2+70.05	8'-00"
2+83.77	4'-00"
2+97.48	8'-00"
3+09.60	12'-00"
3+22.51	16'-00"
3+35.03	20'-00"
3+47.34	24'-00"
3+59.16	28'-00"
3+70.00	32'-00"
3+80.00	36'-00"
3+90.00	40'-00"


STATION ELEVATION CHORD	
4+03.00	8'-00"
4+16.51	4'-00"
4+30.03	8'-00"
4+42.75	12'-00"
4+54.44	16'-00"
4+65.58	20'-00"
4+76.03	24'-00"
4+85.01	28'-00"
4+92.25	32'-00"
5+00.00	36'-00"
5+07.25	40'-00"



THIS DRAWING IS A PART OF THE SPILLWAY
NOT TO SCALE





TYPICAL SECTION OF CUT-OFF TRENCH
SECTION BETWEEN STA 3+40 AND 6+40 AND STA 7+20 AND 9+30




TYPICAL SECTION OF CUT-OFF TRENCH
SECTION BETWEEN STA 6+60 AND 7+00

TRANSITION SECTION FROM STA 6+40 AND 6+60
AND STA 7+00 AND 7+20





TYPICAL SECTION OF EMERGENCY SPILLWAY
WITH DIKE AND BERM

LOOKING DOWNSTREAM
NOT TO SCALE



TYPICAL SECTION OF EMERGENCY SPILLWAY
WITH BERM



LOOKING DOWNSTREAM
NOT TO SCALE




MARTIN CREEK WATERSHED
FLOODWATER RETARDING DAM PA-468
SUSQUEHANNA COUNTY, PENNSYLVANIA
PROFILES - DAM & EMERGENCY SPILLWAY
U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Drawn by: *Joseph Thomas* 5-65
Checked by: *R. A. STALTER* 6-65
Drawn by: *James A. Radtke* 6-65
Checked by: *PA-468-P*

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
PA-468 DAM
SUSQUEHANNA COUNTY COMMISSIONERS
PROFILES
AUGUST 1979
PLATE 4








MARTIN CREEK WATERSHED
FLOODWATER RETARDING DAM PA-468
SUSQUEHANNA COUNTY, PENNSYLVANIA
PROFILES - DAM & EMERGENCY SPILLWAY
U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE


By: *Philip Thomas* 5-65
R. A. STALTER 6-65
Checked: *James R. Radtke* 5-65
PA-468-P

Form SC-210 (November 1959)

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
PA-468 DAM
SUSQUEHANNA COUNTY COMMISSIONERS
PROFILES
AUGUST 1979
PLATE 4



PAVE	GRAVEL
10	15-17
15	18-20
20	21-23
25	24-26
30	27-29
35	30-32
40	33-35
45	36-38
50	39-41
55	42-44
60	45-47
65	48-50
70	51-53
75	54-56
80	57-59
85	60-62
90	63-65
95	66-68
100	69-71





GRADATION LIMITS FOR DRAIN FILL
(SPEC. 105)

- FINE DRAIN FILL
- COARSE DRAIN FILL

5P-132-7	
FILE NUMBER	
RECEIVED IN THE OFFICE OF THE WATER & POWER ENGINEER	
RESOURCES DIVISION, DEPARTMENT OF FORESTS & WATERS	
MARTIN CREEK WATERSHED, A.D. 1965	
<i>Clinton H. Thompson</i> File Clerk	

BE PLACED TO TOP OF DRAIN FILL
STRIPPING LINE



ISOMETRIC OF FOUNDATION DRAIN OUTLET



REC'D	FOR
SEE REPORT NO.	
C. W. Dams	

SEP 14 1965
W. C. Dams


MARTIN CREEK WATERSHED	
FLOODWATER RETARDING DAM	
SUSQUEHANNA COUNTY, PENNSYLVANIA	
FOUNDATION DRAIN DETAILS	
U.S. DEPARTMENT OF AGRICULTURE	
SOIL CONSERVATION SERVICE	
<i>Joseph C. Thomas</i>	5-65
W. A. STALTER	5-65
PA-468-P	

PHASE I INSPECTION REPORT	
NATIONAL DAM INSPECTION PROGRAM	
PA-468 DAM	
SUSQUEHANNA COUNTY COMMISSIONERS	
DRAIN PLAN	
AUGUST 1979	PLATE 5

2



TYPICAL SECTIONS
PAY LIMITS FOR EXCAVATION BETWEEN
NEAT LINES SHOWN



PIPE JOINT DATA


JOINT	DISTANCE FROM RISER	WATER ELEV
1	0.00	102.00
2	6.33	102.08
3	12.67	102.16
4	19.00	102.24
5	25.33	102.32
6	31.67	102.40
7	38.00	102.48
8	44.33	102.56
9	50.67	102.64
10	57.00	102.72
11	63.33	102.80
12	69.67	102.88
13	76.00	102.96
14	82.33	103.04
15	88.67	103.12
16	95.00	103.20

ANTI-SEEP COLLAR DATA


COLLAR	DISTANCE FROM RISER	WATER ELEV
1	0.00	102.00
2	6.33	102.08
3	12.67	102.16
4	19.00	102.24
5	25.33	102.32
6	31.67	102.40
7	38.00	102.48
8	44.33	102.56
9	50.67	102.64
10	57.00	102.72
11	63.33	102.80
12	69.67	102.88
13	76.00	102.96
14	82.33	103.04
15	88.67	103.12
16	95.00	103.20

NOTE: DIMENSIONS OF PIPE ARE BASED
ON NOMINAL SIZE AND DO NOT
INCLUDE CREEP

PROFILE ALONG R OF PRINCIPAL SPILLWAY



SEE SHEETS 4 AND 5 FOR
WALL COLLAR DETAILS



PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM




PA-468 DAM

SUSQUEHANNA COUNTY COMMISSIONERS




MAIN SPILLWAY AND
OUTLET WORKS

AUGUST 1979

PLATE 6



4 (4) - EACH FACE
FIND CIRC. OPENING




REINFORCING STEEL (WGT. COLLAPSE TOP STRUCTURE)


NO.	BAR	WGT.	WGT.	WGT.
1	4 #10	25.12	25.12	50.24
2	4 #10	25.12	25.12	50.24
3	4 #10	25.12	25.12	50.24
4	4 #10	25.12	25.12	50.24
5	4 #10	25.12	25.12	50.24
6	4 #10	25.12	25.12	50.24
7	4 #10	25.12	25.12	50.24
8	4 #10	25.12	25.12	50.24
9	4 #10	25.12	25.12	50.24
TOTAL		200.96	200.96	401.92

CONCRETE WALL (WGT.)
12' x 12' x 12' = 1728 cu ft
150 lb/cu ft = 259,200 lb

SIDE WALL INSIDE STEEL



BAR TYPES



STEEL SCHEDULE

NO.	DESCRIPTION	QTY	LENGTH	NO.	A	B	C	TOTAL FT.
1	6" x 12"	2	5'-4"	2	2'-4"	2'-0"		117.55
2		2	10'-0"	1		2'-0"		20.10
3		4	12'-0"	2	1'-0"	2'-0"		45.10
4		5	15'-0"	1		2'-0"		15.00
5		2	3'-7"	2	1'-7"	2'-0"		7.17
6		24	3'-8"	2	2'-2"	1'-6"		124.67
7		2	8'-0"	1				16.00
8		5	12'-0"	2	8'-0"	2'-0"		50.00
9	WELDED	2	1'-9"	1				5.25
10		1	5'-7"	4	1'-2"	0'-4"	1'-3"	9.25
11		4	6'-7"	4	4'-3"	0'-4"	1'-6"	272.00
12		24	9'-4"	4	7'-6"	0'-4"	1'-6"	147.47
13		10	9'-5"					647.50
14		27	9'-7"	1				642.07
15		4	6'-4"	1				25.33
16		45	9'-1"	1				436.00
17		22	7'-7"	1				155.83
18		5	3'-4"	4	1'-6"	0'-4"	1'-6"	16.47
19		20	6'-3"	1				165.00
20		2	5'-0"	1				9.00
21		2	3'-10"	1				7.67
22		30	5'-3"	1				157.50
23		8	2'-0"	1				16.00
24		8	5'-0"	1				24.00
25		4	4'-0"	1				32.00
26		4	5'-0"	1				40.00
27		8	6'-0"	1				48.00
28	WELDED	1	2'-6"	2	5'-6"	3'-0"		153.00
29		1	2'-4"	2	5'-2"	1'-3"		47.50
30		12	9'-6"	2	6'-0"	3'-6"		124.00
31		4	7'-0"	2	5'-9"	3'-3"		361.00
32		14	8'-6"	2	5'-6"	3'-0"		714.00
33		54	8'-2"	2	5'-4"	2'-0"		441.00
34		2	6'-3"	2	5'-4"	0'-11"		37.50
35		4	9'-10"	2	5'-4"	4'-6"		29.33
36		4	10'-10"	2	5'-4"	5'-6"		43.33
37		4	11'-10"	2	5'-4"	6'-6"		47.33
38		4	12'-10"	2	5'-4"	7'-6"		51.33
39		4	13'-10"	2	5'-4"	8'-6"		55.33
40		4	14'-4"	2	5'-4"	9'-0"		57.33
41		8	14'-1"	1				112.00
42		8	7'-3"	1				58.00
43		12	6'-6"	2	5'-6"	1'-0"		78.00
44		9	3'-3"	1				29.25
45		34	3'-3"	1				117.00
46		46	3'-3"	1				147.50
47		2	5'-0"	1				10.00
48		2	7'-0"	1				14.00
49		12	9'-0"	1				108.00
50		2	11'-0"	1				22.00
51		2	13'-0"	1				26.00
52		2	14'-0"	1				28.00
53		8	6'-3"	1				148.50
54		4	8'-3"	1				115.50
55		52	8'-3"	1				478.50
56		46	8'-3"	1				379.50
57	TOP SLOE	2	15'-6"	1				3.00
58		2	5'-0"	1				15.00
59		4	14'-0"	1				36.00
60		8	14'-0"	1				112.00
61		4	9'-0"	1				23.00
62		4	8'-6"	1				14.00
63	VERTICAL	4	3'-5"	2	4'-3"	0'-6"	1'-6"	25.00
64		4	9'-10"	2	7'-6"	0'-6"	1'-6"	39.00
65	TRANSVERSE	12	7'-0"	1				490.00
66		12	3'-8"	1				275.33
67		20	1'-0"	1				402.00
68		12	7'-6"	1				72.50
69		24	7'-2"	1				408.00
70	VERTICAL	12	4'-0"	1				273.00
71		42	4'-0"	1				231.00

SEE SHEET 12 FOR GENERAL NOTES



MARTIN CREEK WATERSHED
FLOODWATER RETARDING DAM PA-468
SUSQUEHANNA COUNTY, PENNSYLVANIA
STRUCTURAL DETAILS

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Designed by: *James A. Hollingsworth*
Drawn by: *R. MAYS*
Checked by: *R. MAYS*
Date: *6-1-65*
Project: *PA-468-P*

SEP 14 1965

C. H. H. H. H. H.
Chief Engineer

FOR

SEE DETAIL NO.

REC'D

RECEIVED IN THE OFFICE OF THE WATERS
RESOURCES BOARD, U.S. DEPARTMENT OF
WATERS ON THE DAY OF 1965

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM


PA-468 DAM

SUSQUEHANNA COUNTY COMMISSIONERS

MAIN SPILLWAY RISER

AUGUST 1979


PLATE 7



58-132-4


ENGINEERING DIVISION OF THE WATER & POWER
 DEPARTMENT OF AGRICULTURE
 WATERS ON THE DAY OF 1968
 AD 1968
 FOR CLERK

RUC'D FOR
 SEE REPORT NO.
 Div. Engr.



SEP 14 1968
 C. H. McQuinn
 Chief Engineer

PLAN PROFILE OF DIVERSION
 SEE 445 TO 545 &
 SEE 740 TO 840



MARTIN CREEK WATERSHED FLOODWATER RETARDING DAM PA-468 SUSQUEHANNA COUNTY, PENNSYLVANIA PLAN-PROFILE OF DIVERSION U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Designed by A. R. Stalter	Checked by C. CRIST
Date 8-65	Date 6-65
Drawn by R. A. Stalter	Checked by
Date 6-65	Date
Project No. PA-468-P	Sheet No. 8

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM	
PA-468 DAM	
SUSQUEHANNA COUNTY COMMISSIONERS	
DIVERSION SYSTEM	
AUGUST 1979	PLATE 8

2

SUSQUEHANNA RIVER BASIN
BROOKLYN RUN, SUSQUEHANNA COUNTY
PENNSYLVANIA

PA-468 Dam

NDI ID No. PA-00046
DER ID No. 58-132
SCS ID No. PA-468

SUSQUEHANNA COUNTY COMMISSIONERS
PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

AUGUST 1979

APPENDIX A
CHECKLIST- ENGINEERING DATA

CHECKLIST

NAME OF DAM: PA-468 Dam

ENGINEERING DATA

NDI ID NO.: PA-00056 DER ID NO.: 58-132DESIGN, CONSTRUCTION, AND OPERATION
PHASE ISheet 1 of 4

ITEM	REMARKS
AS-BUILT DRAWINGS	Complete set of design drawings available. As-built conditions shown in SCS files.
REGIONAL VICINITY MAP	See Plate 1.
CONSTRUCTION HISTORY	Constructed 1966-1967 by Susquehanna County Commissioners.
TYPICAL SECTIONS OF DAM	See Plate 2.
OUTLETS: Plan Details Constraints Discharge Ratings	See Plates 3, 6, and 7. See Appendix C for discharge ratings.

ENGINEERING DATA

Sheet 2 of 4

ITEM	REMARKS
RAINFALL/RESERVOIR RECORDS	None.
DESIGN REPORTS	Complete design folder in SCS files. Each section marked "void" except hydrology and hydraulics section.
GEOLOGY REPORTS	Geologic report in design folder. Summary presented in Appendix E.
DESIGN COMPUTATIONS: Hydrology and Hydraulics Dam Stability Seepage Studies	Complete H & H computations. Stability analysis for embankment. No seepage studies.
MATERIALS INVESTIGATIONS: Boring Records Laboratory Field	Complete investigation.
POSTCONSTRUCTION SURVEYS OF DAM	None.

ENGINEERING DATA

Sheet 3 of 4

ITEM	REMARKS
BORROW SOURCES	Shown on Plate 2.
MONITORING SYSTEMS	None.
MODIFICATIONS	None.
HIGH POOL RECORDS	None.
POSTCONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM: Description Reports	None.

ENGINEERING DATA

Sheet 4 of 4

ITEM	REMARKS
MAINTENANCE AND OPERATION RECORDS	Annual operation and maintenance inspection reports by SCS.
SPILLWAY: Plan Sections Details	See Plates 3, 6 and 7.
OPERATING EQUIPMENT: Plans Details	Available.
PREVIOUS INSPECTIONS Dates Deficiencies	1970: No deficiencies. 1971: No deficiencies. 1972: No deficiencies. 1973: No deficiencies. 1974: No deficiencies. 1975: No deficiencies. 1976: No deficiencies.
	1977: Impact basin wall chipped; brush in diversion inlet; fence cut. 1978: Impact basin wall chipped; brush in diversion inlet.

UNITED STATES GOVERNMENT

Memorandum

TO : Craig M. Right, State Conservation DATE: April 30, 1965
Engineer, SCS, Harrisburg, Pennsylvania 17101

FROM : Rey S. Decker, Head, Soil Mechanics Laboratory,
SCS, Lincoln, Nebraska 68508

SUBJECT: ENG 22-5, Pennsylvania WP-08, Martin's Creek, Site No. PA-468
(Susquehanna County)

ATTACHMENTS

1. Form SCS-354, Soil Mechanics Laboratory Data, 1 sheet.
2. Form SCS-355, Triaxial Shear Test Data, 1 sheet.
3. Form SCS-352, Compaction and Penetration Resistance Report, 3 sheets.
4. Form SCS-353, Filter Design, 1 sheet.
5. Investigational Plans and Profiles.

DISCUSSIONFOUNDATION

- A. Classification: The foundation material at this site consists primarily of a dense glacial till that is logged as ML.

Bedrock was encountered in DH 2 at ϵ Station 4+50 on the left abutment. The bedrock drops off sharply left of ϵ Station 4+50. In DH 302 bedrock was encountered at a 68-foot depth. DH 302 is in the bottom of the valley at ϵ Station 6+80.

Bedrock was not encountered at the investigational depths on the left abutment.

Samples submitted from Test Hole 602 are classified GC-GM and SC-SM

- B. Blow Count: The till is relatively dense as indicated by blow count tests. Tests below water table resulted in blow counts generally in excess of 40 blows/ft.

The GM and SM alluvium in DH 301, 302 and 303 had blow counts ranging from 18 to 65 blows/ft.

The lake sediment behind the small dam has a low blow count of 2 blows/ft.

- C. Shear Strength and Consolidation: The blow count tests indicate a foundation with high strength and low consolidation potential.
- D. Permeability: Field permeability tests were made and are reported in the site investigational report.

2 -- Craig M. Right -- 4/30/65

Rey S. Decker

Subj: ENG 22-5, Pennsylvania WP-08, Martin's Creek, Site No. PA-468
(Susquehanna County)

EMBANKMENT

- A. Classification: The samples submitted from the emergency spillway and from the borrow area are sandy and gravelly materials that are classed as SM and GM. The samples contain from about 25 to 40 percent gravel and 20 to 40 percent fines. The liquid limits are less than 20 and the PI's are less than 3.
- B. Compacted Density: Standard Proctor compaction tests were made on the minus No. 4 fraction. The compacted densities obtained ranged from 123 p.c.f. to 128 p.c.f.
- C. Shear Strength: A triaxial shear test was made on Sample 65W2462 to represent the materials submitted. The test was made on the minus No. 4 fraction compacted to 95 percent of standard Proctor density. The test was made at saturation and the consolidated, undrained values obtained were $\phi = 32^\circ$, $c = 0$. The test values are considered to be representative of these materials for a placement density of 95 percent of standard Proctor and are suggested for design.
- D. Permeability: A permeability test was made on the minus No. 4 fraction compacted to 95 percent of standard Proctor density. The test was made under a 2000 p.s.f. load and the permeability rate obtained was 0.02 ft./day.

SLOPE STABILITY

The stability of the upstream slope was checked with an infinite slope method of analysis. The factor of safety for a 3:1 slope is 0.94 considering horizontal flow lines, and $F_s = 1.03$ considering parallel flow lines.

A 3 1/2:1 upstream slope has a factor of safety of 1.12 considering horizontal flow and $F_s = 1.20$ considering parallel flow.

The proposed 2:1 downstream slope was checked with an infinite slope (dry slope condition) analysis and the factor of safety obtained was 1.25.

The factor of safety obtained for the 2:1 downstream slope with a sliding wedge method of analysis was 3.0. This analysis considered a drain at $c/b = 0.6$.

SETTLEMENT ANALYSIS

With the exception of the small dam and the recent lake sediment the consolidation potential of the foundation material is expected to be low and differential settlement is not expected to be a problem.

3 -- Craig M. Right -- 4/30/65

Rey S. Decker

Subj: ENG 22-5, Pennsylvania WP-08, Martin's Creek, Site No. PA-468
(Susquehanna County)

RECOMMENDATIONS

- A. Foundation Preparation: We concur with the proposal to remove the small dam and the recent lake sediment behind it. The lake sediment is a 2 blow/ft. material. Normal site preparation is expected to be adequate for the rest of the foundation.
- B. Cutoff Trench: A shallow cutoff trench is suggested. A minimum trench depth of 5 feet is recommended to insure that the trench bottoms below the zone affected by roots, rodents, cracking, etc. The trench backfill should consist of the most plastic material available compacted to a minimum of 95 percent of standard Proctor density with the control based on the minus 4 fraction.
- C. Principal Spillway: The proposed location is in the bottom of the narrow V-shaped valley. At this location dense till occurs at a depth of less than 8 feet and the conduit can be bedded directly on the till throughout its entire length. Placement in this manner would provide a uniform foundation on essentially a non-yielding foundation.

If the conduit is not bedded on till at this location, over-excavation and backfill will probably be required in order to obtain a uniform foundation.

- D. Drain: A drain is recommended to control the phreatic line in the embankment and also to provide a safe outlet for underseepage.

Positive control of the phreatic line is required with the proposed 2:1 downstream slope. Therefore, we recommend a partial blanket drain in conjunction with a shallow trench drain. The trench drain should have a minimum depth of 5 feet and should be located at about $c/b = 0.6$. The blanket drain should extend upstream from the trench drain. A blanket width in the range of 10 feet is suggested.

The suggested filter limits are shown on the attached Form SCS-353.

- E. Embankment Design:

1. Placement of Materials. The materials from the borrow area and from the emergency spillway are very similar and the materials from both sources may be used anywhere in the fill.

Although some of the material will contain slightly more than 35 percent gravel, we recommend that the density control be based on the minus 4 fraction in order to insure uniform permeability in the embankment.

4 -- Craig M. Right -- 4/30/65

Rey S. Decker

Subj: ENG 22-5, Pennsylvania WP-08, Martin's Creek, Site No. PA-468
(Susquehanna County)

All of the embankment material should be placed at a minimum of 95% of standard Proctor density with the control based on the minus 4 fraction.

The placement moisture content should be on the wet side of optimum.

2. Slopes. On the basis of the test data and stability analyses, the following slopes are required in order to obtain acceptable factors of safety.

a. Upstream - 3 1/2:1.

b. Downstream - 2:1 with control of the phreatic line.

- F. Settlement: An overfill allowance of 1.25 ft. ^{1.25' ~ 2.5' / 0} is suggested to compensate for residual consolidation within the fill and the foundation.

Prepared by:

Lorn P. Dunnigan

Reviewed and Approved by:

Roland B. Phillips

Attachments

cc: Craig M. Right (5)
H. M. Kautz, Upper Darby, Pa. (2)

SUSQUEHANNA RIVER BASIN
BROOKLYN RUN, SUSQUEHANNA COUNTY
PENNSYLVANIA

PA-468 Dam

NDI ID No. PA-00046
DER ID No. 58-132
SCS ID No. PA-468

SUSQUEHANNA COUNTY COMMISSIONERS
PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

AUGUST 1979

APPENDIX B
CHECKLIST - VISUAL INSPECTION

CHECKLIST

VISUAL INSPECTION

PHASE I

Name of Dam: PA-468 Dam County: Susquehanna State: Pennsylvania
NDI ID No.: PA-00056 DER ID No.: 58-132

Type of Dam: Homogeneous earth fill. Hazard Category: High

Date(s) Inspection: 18 July 1979 Weather: Overcast Temperature: 70°
Rain during inspection.

Pool Elevation at Time of Inspection: 1277.1 msl/Tailwater at Time of Inspection: 1190.0 msl

Inspection Personnel:

D.A. Wolf (GECC)
D.B. Ebersole (GECC)

D.B. Wilson (GECC) Recorder

EMBANKMENT

Sheet 1 of 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None apparent.	Upstream slope has heavy grass cover; downstream slope has crownvetch cover.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None.	
SLOUGHING OR EROSION: Embankment Slopes Abutment Slopes	None.	
CREST ALIGNMENT: Vertical Horizontal	See survey data at end of Appendix B.	
RIPRAP FAILURES	No riprap.	Thick grass cover on upstream slope.

EMBANKMENT

Sheet 2 of 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT WITH: Abutment Spillway Other Features	No deficiencies.	
ANY NOTICEABLE SEEPAGE	None.	
STAFF GAGE AND RECORDER	None.	
DRAINS	6-inch BCCMP outlet at each side of impact basin.	Slight clear discharge from each outlet: Left outlet \approx 0.3 gpm Right outlet : slight trickle
MISCELLANEOUS	2 small shrubs on downstream slope	

OUTLET WORKS (MAIN SPILLWAY AND OUTLET WORKS)

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Outlet conduit in good condition. Joint separation increases progressively toward maximum section.	30-inch diameter concrete conduit. Maximum joint opening approx. 1" and located near $\frac{1}{2}$ of dam.
INTAKE STRUCTURE (Riser)	Concrete and metals in good condition.	
OUTLET STRUCTURE (Impact Basin)	Minor spalling of concrete on inside left wall; large rocks in basin; conduit separated from headwall slightly.	Slight clear flow visible where outlet conduit is separated from headwall.
OUTLET CHANNEL	No deficiencies.	
EMERGENCY GATE	No gates.	Could not inspect bolted closure at end of 12" ϕ steel pipe due to flow of water.

UNGATED SPILLWAY (AUXILIARY SPILLWAY)

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	None.	
APPROACH CHANNEL	Minor amount of brush.	
DISCHARGE CHANNEL	No deficiencies.	
BRIDGE AND PIERS	None.	

INSTRUMENTATION

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHER	None.	

RESERVOIR AND WATERSHED

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Generally steep and grass covered.	No signs of instability.
SEDIMENTATION	No known problems.	
WATERSHED DESCRIPTION	Approximately 95% farmland.	Reservoir area used as pasture.
DIVERSION SYSTEM	Generally in good condition, but the inlet area for 54-inch pipe had heavy brush.	


DOWNSTREAM CHANNEL

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION: Obstructions Debris Other	No obstructions; V-shaped valley.	
SLOPES	Steep.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	Community of Brooklyn located 0.1 mile downstream.	Approx. 25 low-lying dwellings located in Brooklyn.


GANNETT FLEMING CORDRY
AND CARPENTER, INC.
HARRISBURG, PA.

SUBJECT PH No 468 DAM FILE NO. _____
Profile - TOP of DAM SHEET NO. _____ OF _____ SHEETS
 FOR _____
 COMPUTED BY _____ DATE _____ CHECKED BY _____ DATE _____




PH No. 468 DAM
Profile - TOP of DAM
SCALES: HORIZ - 1" = 100'
VERT - 1" = 4'

SUBJECT MH 10768 P-1 FILE NO. _____
L.A.C. 10768 S-D SHEET NO. _____ OF _____ SHEET
 FOR _____
 COMPUTED BY _____ DATE _____ CHECKED BY _____ DATE _____



B-10



NOT TO SCALE

PHASE I INSPECTION REPORT
 NATIONAL DAM INSPECTION PROGRAM
 PA-468 DAM
 SUSQUEHANNA COUNTY COMMISSIONERS
 RESULTS OF VISUAL INSPECTION
 AUGUST 1979 PLATE B-1

SUSQUEHANNA RIVER BASIN
BROOKLYN RUN, SUSQUEHANNA COUNTY
PENNSYLVANIA

PA-468 Dam

NDI ID No. PA-00046
DER ID No. 58-132
SCS ID No. PA-468

SUSQUEHANNA COUNTY COMMISSIONERS
PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

AUGUST 1979

APPENDIX C
HYDROLOGY AND HYDRAULICS


APPENDIX C

HYDROLOGY AND HYDRAULICS

In the recommended Guidelines for Safety Inspection of Dams, the Department of the Army, Office of the Chief of Engineers (OCE), established criteria for rating the capacity of spillways. The recommended Spillway Design Flood (SDF) for the size (small, intermediate, or large) and hazard potential (low, significant, or high) classification of a dam is selected in accordance with the criteria. The SDF for those dams in the high hazard category varies between one-half of the Probable Maximum Flood (PMF) and the PMF. If the dam and spillway are not capable of passing the SDF without overtopping failure, the spillway capacity is rated as inadequate. If the dam and spillway are capable of passing one-half of the PMF without overtopping failure, or if the dam is not in the high hazard category, the spillway capacity is not rated as seriously inadequate. A spillway capacity is rated as seriously inadequate if all of the following conditions exist:

- (a) There is a high hazard to loss of life from large flows downstream of the dam.
- (b) Dam failure resulting from overtopping would significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure.
- (c) The dam and spillway are not capable of passing one-half of the PMF without overtopping failure.

MARTIN CREEK WWS
PA-448
STAGE-STORAGE, AREA CURVES



1/13/59

FREE GOV

HYDROGRAPH COMPUTATION FORM

Watershed MARTIN CREEK State PA.Structure Site or Sub-area #1Storm Distribution Curve 13 Hydrograph Family 1D.A. 0.378 sq.mi. Pt. Rainfall ^{2.5 x 10} 25.0 inches Aerial Rainfall 24.5 inchesR.O. Condition II R.O. Curve No. 77 Storm Duration or Freq. 6 hr. $T_c = .71$ hrs. $Q = 21.2$ inches $T_p = 0.686$ $T_c = .5$ $T_o = 5.6$ hr. $\frac{T_o}{T_p}$ Computed = 11.2 $\frac{T_o}{T_p}$ used: 10 Revised $T_p = .56$ hr. $Q_p = \frac{484 A}{\text{Rev. } T_p} = 327$ c.f.s. $q_p \times Q = 6940$ c.f.s. T (Column) $= \frac{1}{T_p} \times \text{Rev. } T_p$ q (Column) $= \frac{q_c}{q_p} (q_p Q)$ Table 3.21-7 (Sheet 25 of 52) Check: $Q = \frac{(\sum t)(\sum q)}{645 A}$

Line No.	$\frac{t}{T_p}$	$\frac{q_c}{q_p}$	T hours	8 c.f.s.	Line No.	$\frac{t}{T_p}$	$\frac{q_c}{q_p}$	T hours	8 c.f.s.
1	0	0	0	0	21				
2	.56	.002	.31	14	22				
3	1.12	.013	.63	90	23				
4	1.68	.027	.94	187	24				
5	2.24	.047	1.25	326	25				
6	2.80	.071	1.57	483	26				
7	3.36	.115	1.88	798	27				
8	3.92	.178	2.20	1229	28				
9	4.48	.234	2.51	2734	29				
10	5.04	.322	2.82	2235	30				
11	5.60	.235	3.14	1631	31				
12	6.16	.174	3.45	1208	32				
13	6.72	.136	3.76	941	33				
14					34				
15					35				
16					36				
17					37				
18					38				
19					39				
20					40				

SCS Freeboard Storm Data:

Rainfall = 24.5 inches

Runoff = 21.2 inches

Peak Inflow = 2734 cfs

PMF Data for PA-46B Site (Hydromet. 40):

Index Rainfall = 22.15 inches

Geographic Adjustment Factor = 95%

Distribution:

6 hr	118%
12 hr	127%
24 hr	136%
48 hr	142%
72 hr	145%

Hop Brook Reduction Factor = 0.80

Revised PMF index rainfall = $22.15 \times .95 \times .80 = 16.83$ inches

Total 6-hr. rainfall = $(1.18)(16.83) = 19.86$ inches

Runoff from 6-hr rainfall = $19.86 - (6)(0.05) = 19.56$ inches
(Initial abstraction of 1" occurred early in PMF)

Since small watersheds (i.e. 0.4 mi²) are only sensitive to peak rainfall periods, it is reasonable to compare the Freeboard Storm and the PMF based on the maximum 6-hour runoff. Since the Freeboard Storm runoff (21.2 inches) is greater than the 6-hour runoff from the PMF (19.56") and because the SCS unit hydrograph is conservative, the Freeboard Storm flood is an acceptable substitute for the PMF.

MAXON CO. EX W/S PA-468

STAGE-DISCHARGE COMPUTATIONS

[illegible]

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

15-11-64 RD 5-1-64

15

101

H_2	$P_{w1} = 46.5 \text{ in } \frac{1}{2}$	$P_1 + P_2$	H_0 Elevation CH. 100	H_1	$S_A = 19.5 \text{ in } \frac{1}{2}$	q	H_p * 54.77 65.13 $L = 1.00$	d_c 54.14 $L = 5.5$	N_1 $6+3 d_c = 75+2 d_c$	$Q = W_g$	P_{total}	$P_{net} = P_{total} - Q_{net} (-3)$
								Auxiliary Spillway →				
		0									0	0
		13									13	10
		18									18	15
		20									20	15
		23									23	15
		26									26	15
		30									30	15
		34									34	15
		38									38	15
		42									42	15
		46									46	15
		50									50	15
		54									54	15
		58									58	15
		62									62	15
		66									66	15
		70									70	15
		74									74	15
		78									78	15
		82									82	15
		86									86	15
		90									90	15
		94									94	15
		98									98	15
		102									102	15
		106									106	15
		110									110	15
		114									114	15
		118									118	15
		122									122	15
		126									126	15
		130									130	15
		134									134	15
		138									138	15
		142									142	15
		146									146	15
		150									150	15
		154									154	15
		158									158	15
		162									162	15
		166									166	15
		170									170	15
		174									174	15
		178									178	15
		182									182	15
		186									186	15
		190									190	15
		194									194	15
		198									198	15
		202									202	15
		206									206	15
		210									210	15
		214									214	15
		218									218	15
		222									222	15
		226									226	15
		230									230	15
		234									234	15
		238									238	15
		242									242	15
		246									246	15
		250									250	15
		254									254	15
		258									258	15
		262									262	15
		266									266	15
		270									270	15
		274									274	15
		278									278	15
		282									282	15
		286									286	15
		290									290	15
		294									294	15
		298									298	15
		302									302	15
		306									306	15
		310									310	15
		314									314	15
		318									318	15
		322									322	15
		326									326	15
		330									330	15
		334									334	15
		338									338	15
		342									342	15
		346									346	15
		350									350	15
		354									354	15
		358									358	15
		362									362	15
		366									366	15
		370									370	15
		374									374	15
		378									378	15
		382									382	15
		386									386	15
		390									390	15
		394									394	15
		398									398	15
		402									402	15
		406									406	15
		410									410	15
		414									414	15
		418									418	15
		422									422	15
		426									426	15
		430									430	15
		434									434	15
		438									438	15
		442									442	15
		446									446	15
		450									450	15
		454									454	15
		458									458	15
		462									462	15
		466									466	15
		470									470	15
		474									474	15
		478									478	15
		482									482	15
		486									486	15
		490									490	15
		494									494	15
		498									498	15
		502									502	15
		506									506	15
		510									510	15
		514									514	15
		518									518	15
		522									522	15
		526									526	15
		530									530	15
		534									534	15
		538									538	15
		542									542	15
		546									546	15
		550									550	15
		554									554	15
		558									558	15
		562									562	15
		566									566	15
		570									570	15
		574									574	15
		578									578	15
		582									582	15
		586									586	15
		590									590	15
		594									594	15
		598									598	15
		602									602	15
		606									606	15
		610									610	15
		614									614	15
		618									618	15
		622									622	15
		626									626	15
		630									630	15
		634									634	15
		638									638	15
		642									642	15
		646									646	15
		650									650	15
		654									654	15
		658									658	15
		662									662	15
		666									666	15
		670									670	15
		674									674	15
		678									678	15
		682									682	15
		686									686	15
		690									690</	

SUSQUEHANNA RIVER BASIN
BROOKLYN RUN, SUSQUEHANNA COUNTY
PENNSYLVANIA

PA-468 Dam

NDI ID No. PA-00046
DER ID No. 58-132
SCS ID No. PA-468

SUSQUEHANNA COUNTY COMMISSIONERS
PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

AUGUST 1979

APPENDIX D
PHOTOGRAPHS

PA-468 DAM




A. Upstream Slope of Embankment.



B. Downstream Slope of Embankment.

PA-468 DAM



C. Main Spillway Riser.



D. Main Spillway Impact Basin
and Foundation Drain Outlet.



E. Auxiliary Spillway Approach Channel.



F. Auxiliary Spillway Exit Channel.

SUSQUEHANNA RIVER BASIN
BROOKLYN RUN, SUSQUEHANNA COUNTY
PENNSYLVANIA

PA-468 Dam

NDI ID No. PA-00046
DER ID No. 58-132
SCS ID No. PA-468

SUSQUEHANNA COUNTY COMMISSIONERS
PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

AUGUST 1979

APPENDIX E
GEOLOGY

APPENDIX E

GEOLOGY

1. General Geology. The damsite and reservoir are located in Susquehanna County. Susquehanna County lies north of the Wisconsin Terminal Moraine and, with the exception of the summit of Elk Hills, was entirely covered by ice. Deposits of glacial drift of variable thickness cover the County except where they have been removed by erosion. The County is drained entirely by the north branch of the Susquehanna River and its tributaries. The Susquehanna River enters Susquehanna County from New York near the northeast corner of the County and re-enters New York just north of the town of Great Bend, Pa. The river does not again re-enter the County but comes within four miles of the southwest border. As the County lies entirely north of the glacial border, there are abundant, undrained areas occupied by swamps and lakes. A geologic map is presented on Plate E-1.

The rock formations exposed in Susquehanna County range in age from the Post-Pottsville of Pennsylvanian age to the Chemung of Devonian age. The youngest formations, the Post-Pottsville and Mauch Chunk, are exposed only in the southeast corner of the County. The older rocks are exposed along the western and northern boundaries.

The major structural feature of the region is the Lackawanna Syncline, which terminates in the southeast corner but whose axis turns and runs due north along the Wayne County line. Along the west side of this synclinal axis, the strata dip steeply to the southeast. Over the next four to five miles westward, the strata flatten out to nearly horizontal. Toward Tunkhannock Creek to the northwest, the strata reverse dip on the axis of an anticline that continues southwestward as far as Union and Clinton Counties. The rocks in the remainder of the County lie nearly horizontal but are folded locally into minor anticlines. The Wilmont Anticline enters at the southwest corner of the County and extends across Auburn Township. Its southward dip rarely exceeds 1°, so that the strata in the southern part of the County are nearly horizontal.

2. Site Geology. PA-468 Dam is underlain by the Susquehanna Group of Devonian age. A report dated September 3, 1965 states that the foundation material consists primarily of a dense glacial till. Bedrock was encountered at extensive depth. The Susquehanna Group is a complex unit of conglomerates, sandstones, siltstones and shales. From the base of this unit to the top, the following changes occur in northeastern Pennsylvania: (1) grain size increases from bottom to top; (2) average thickness of beds increases upwards; (3) percent red color in shales increases upwards; and (4) in general, percent silica in rocks increases upwards. Bedding is usually well-developed with thicknesses up to sixteen feet in the coarser beds. Joints are usually open and steeply dipping or vertical. The shales disintegrate rapidly when exposed to the atmosphere. The siltstones, sandstones, and conglomerates are moderately resistant to weathering. There are abundant swamps and lakes in the area, which is characteristic of this glaciated low plateau section in which the dam is located.

only

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

Penna. County Susquehanna Watershed Martin Creek Tributary Hop Bottom Creek
 Project number PA-468 Site group I Structure class C Investigated by Ronald C. Peep Geologist Date 2/15/65
 (signature and title)

INTERPRETATIONS AND CONCLUSIONS

Interpretation

This site is excellent from all aspects of geology. Rock was encountered on the right abutment near the surface and at depth across the site from station 4+50. A glacial till (ML) has filled the valley and through soil formation a hardpan (SM) layer has developed upon the till. Very little rock excavation will be required in the emergency spillway. Borrow is very abundant and of very good quality.

Foundation

The foundation is excellent with no consolidation problems expected. Differential settlement near the rock drop off at station 4+50 will not occur because of the high density and compactness of the till. Bearing strength of the till and hardpan is very high. Permeability of the hardpan layer is believed to be slight and the till is essentially zero. It is suggested that a positive cutoff be employed through the top ML layer on the right abutment and at least 2.0 feet on the left abutment. Hardpan will be sufficiently impervious to act as a base for the cutoff. Consideration should be given to the complete removal of the alluvial zone as mentioned under the principal spillway section. This zone could allow considerable leakage and possible piping.

Principal Spillway

The recent alluvium (SM and GM) is permeable and less dense than the till. Consideration should be given to the removal of this eight foot zone of alluvium. This would mean excavation only as wide as the present stream channel which is the limit of the material. The till on the other hand is very dense with a very high bearing strength. The conduit could either be placed directly on the till or on till backfill. Either method would provide a suitable foundation. The small amount of alluvium removed could be mixed with the borrow material and used in the fill.

Borrow

No detailed computations on the amount of borrow have been made, but rough calculations shows that more than double the required amount is present. An unusual situation is present here inasmuch as the removal of borrow must create a sediment pool of 3.5 acre feet. In view of this special problem the actual delineation of where to obtain borrow is left to the discretion of the design engineer, who can then plan its removal from the areas where more storage is required.

It is suggested that the top 0.5 feet of soil be removed to the spoil area. This leaves 1.0 to 1.5 feet of ML material which can be mixed with the underlying hardpan. This material (ML and SM) should go into the shell of the structure. The till can best be utilized as core material.

- 2 -


Many road cuts in the area show shear failures due to over steepening slopes. Not less than 3:1 side slopes in the borrow area are advisable without the use of berms.

Emergency Spillway

Material removed from the spillway is probably best suited for use in the shell of the proposed structure. This would be based on the use of a core of the denser till. The rock which will be removed is not very strong and can be ripped to a minimum depth of 5.0 feet below the top of the weathered zone. It is questionable if ripping can be successfully continued beyond this depth.

Proposed Diversion PA-468b

Four test pits were dug along the centerline of the proposed diversion. Rock was not encountered and no problems are anticipated during construction.



PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

PA-468 DAM
SUSQUEHANNA COUNTY COMMISSIONERS

GEOLOGIC MAP

AUGUST 1979

PLATE E-1